

Site 5: Water Well at RED HORSE Beddown Area. A former drinking water well was located within the RED HORSE Beddown area .During the Preliminary Assessment, the installation confirmed there was one drinking water well in the RED HORSE Beddown Area, and this water well was properly abandoned in May 2012. According to the installation, the Ohio Department of Natural Resources permitted the former well to be closed through pressure grouting. No soil or groundwater samples were required by Ohio EPA to close out this site. A copy of the well closure document was found during the December 2013 Preliminary Assessment. No further investigation is required and administrative closure of this Area of Concern was recommended.